

Port of London Authority Chart Correction Advice Date: 21st July 2017

CCA No: 2017/20




Chart:Limehouse. Reach

PLA Chart No. 320 HO Ref No. 113-320-059 Previous Chart Correction: 2016/16

The accompanying block correction shows

New, temporary Easterly Cardinal Mark located off Convoys Wharf This warns of a sunken pontoon



For further information see the PLA hydrographic service website:

http://www.pla.co.uk/Safety/PLA-Hydrographic-Service-Published-Surveys